

### Racer's Conversion Chart

B&S (Gauge)	Inch (Decimal)	Millimeter (mm)	Inch (fraction)		B&S (Gauge)	Inch (Decimal)	Millimeter (mm)	Inch (fraction)
1	0.289	7.348			15	0.057	1.449	
2	0.258	6.543			16	0.051	1.291	
	0.250	6.350	1/4			0.047	1.191	3/64
	0.234	5.953	15/64		17	0.045	1.149	
3	0.229	5.827			18	0.040	1.024	
	0.219	5.556	7/32		19	0.036	0.912	
4	0.204	5.189			20	0.032	0.812	
	0.203	5.154	11/64			0.031	0.795	1/32
	0.188	4.762	3/16		21	0.028	0.723	
5	0.182	4.621			22	0.025	0.644	
	0.172	4.366	11/64		23	0.023	0.573	
6	0.162	4.115			24	0.020	0.511	
	0.156	3.969	5/32		25	0.018	0.455	
7	0.144	3.664			26	0.016	0.405	
	0.141	3.572	9/64			0.016	0.396	1/64
8	0.128	3.263			27	0.014	0.360	
	0.125	3.175	1/8		28	0.013	0.321	
9	0.114	2.906			29	0.011	0.286	
	0.109	2.778	7/64		30	0.010	0.255	
10	0.102	2.588			31	0.0089	0.226	
	0.094	2.381	3/32		32	0.0080	0.200	
11	0.091	2.304			33	0.0071	0.180	
12	0.081	2.052			34	0.0063	0.160	
	0.078	1.984	5/64		35	0.0056	0.142	
13	0.072	1.828			36	0.0050	0.130	
14	0.064	1.628			37	0.0045	0.114	
	0.063	1.588	1/16		38	0.0040	0.100	